

# Giant Travelling Clam

## International Flying Kit

mise en réseau :

utilisation avec un câble croisé :

donner une adresse fixe à l'ordinateur en 192,168,0,xxx en allant dans « centre réseau et partage » et modifier dans propriétés/TCP/IP V4


optimiser l'ordinateur : enlever les programmes qui démarrent tout seul au démarrage : menu programme/démarrage et regedit/run

système/options avancées : « laisser windows pour de meilleurs performances »


tous les composants fonctionnent en 5V

## I. Schémas :


L'interface est conçu autour d'un MEGA2600 qui reçoit les informations des périphériques via I<sup>2</sup>C puis les transmet en OSC sur le réseau Ethernet.




## mainboard




## deplacement sensor + LDR's




## MPG + 6buttons




## RFID reader





## Pedal



## Gyroscope



## external button box



## II. OSC messages

Giant Travelling Clam: 192, 168, 0, 79 /GTC

### A. Outward messages :

#### Morph datas

morph datas are received by the mainboard and send via OSC after treatment.

4 different modes are available :

Mode 0 : basic mode - up to 16 fingers are detected

/GTC/MD0 <finger ID><xPos><yPos><total force><area><orientation>

/GTC/MD0/NCT <number of contacts><bitwise state of fingers>

( ex : finger 1 => state = 0000000000000001

Mode 1 : gesture 1 – detect number of fingers on board, send position of first finger and distance between first and last finger

/GTC/MD1 <finger recog><fingers state><xPos 1rst finger><yPos 1rst finger>  
 <total force><orientation><distance inter fingers>

Mode 2 : gesture 2 – 10 x 7 grid detection on first finger, angle detection between first and second finger

/GTC/MD2 <cell number><finger state><fingerMoveX><fingerMoveY><velocity><total force><total area><inter finger angle>< distance inter fingers>

Mode 3 : cell split - TODO

/GTC/MD3


Mode 4 : 8 vertical faders

/GTC/MD4/FD(0 to 7) <xPos><yPos><contactID><total force><area><orientation>

/GTC/MD4/NCT <number of contacts><bitwise state of fingers>

**2 pedal buttons + 20 external box buttons + main's 6 buttons:**

/GTC/BP/00 <état logique> to /GTC/BP/27 <état logique>



**displacement sensor:**

/OLA/Dist < valeur de 0 à 511>

**LDR's and pedal position:**

/OLA/ANA <LDR0> <LDR1> <LDR2> <PEDAL val>(0 - 511)

**Manual Pulse Generator:**

/GTC/MPG <angular speed> <totalisation warp> <totalisation stop> <angular acceleration>

**RFID TAG**

/GTC/TAG <val> <val> <val> <val> <val> <val> <val> (5 or 7 val according to Tag)

**MODE selector**

GTC/MODE <int 0 to 7>

**active sensing**

/GTC/sens <secondes écoulées depuis la dernière mise en marche>

## Setup control

send states of the I2C slaves :

GTC/SETUP <string>

exemples : "Pedal connected", "WARNING Pedal not connected",

## B. Inward messages


### Morph MODE select

GTC/MODE <int 0 to 4>

### 17 LED's on button box + 6 LED's around MPG

/GTC/SLD <LED# from 0 to 22> <0 or 1>

if LED# is set to 255, all LEDs are switched altogether.



### 1 multicolor indicator light

/GTC/VOZ <RED 0 to 16> <GREEN 0 to 16> <BLUE 0 to 16>

### 1 red indicator light

/GTC/VOY <0 to 255>

**analog sensor sending frequency (3LDRs, displacement sensor)**

/GTC/AnaCde <0 à 65 515 ms>

### reset of minimum and maximum for 3 LDRs :

le microcontrôleur détecte automatiquement le niveau min et max d'éclairément pour réaliser la mise à l'échelle des données envoyées par GTC/ANA . En cas de changement des conditions d'éclairément ambiant, il convient d'envoyer un message de reset des min/max.

/GTC/reset <dumy>

### MPG setup :

**max value of totalisation 0-65535 (warp)**

/GTC/MPG/S2 <set valeur 0 à 65535>

**max value of totalisation 0-65535 (stop)**

/GTC/MPG/S3 <set valeur 0 à 65535> si la valeur est inférieure à la valeur de la butée basse, val = min, si la valeur est supérieure à la butée haute, val = max.

**min and max stops setup :**

/GTC/MPG/M3 <min 0 à 65535> <max 0 à 65535>